


Industry sector emissions



- **2°C target** industry emissions decrease almost as quickly as total emissions
- **1.5°C target** runs the risk of hard-to-abate industry sector emissions
- Key factors increasing risk
 - Developed and industrialized countries reduce emissions too slowly
 - Key mitigation options can not be realized quickly enough: electrification, non-fossil feedstocks, CCUS, material efficiency and recycling

